

Normalmessur Metall Walcker 1907 aus Messurbuch OW

		halber U	Ø	U
		$x=1/2U$	$d=(x/\pi)*2$	U
		mm	mm	mm
8'	18 C	260	165,52	520
	19 Cs	249	158,52	498
	20 D	238	151,52	476
	21 Ds	228,5	145,47	457
	22 E	218,5	139,10	437
	23 F	209,5	133,37	419
	24 Fs	201,5	128,28	403
	25 G	193	122,87	386
	26 Gs	184	117,14	368
	27 A	176	112,05	352
	28 B	169	107,59	338
29 H	162	103,13	324	
4'	30 c	155	98,68	310
	31 cs	148,5	94,54	297
	32 d	142	90,40	284
	33 ds	137	87,22	274
	34 e	131,5	83,72	263
	35 f	125,5	79,90	251
2'	42 c1		61,5	
1'	54 c2		38,5	